

Inspection Record Printed: 07/26/2023

Inspection Date: Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: NOTE

Inspector:

Passed? No

Complete the items listed below:

Hold all inspections until owner calls.



Inspection Record Printed: 07/26/2023

Inspection Date: 08/15/2008 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: MECHANICAL ROUGH-IN

Inspector: Larry Brown

Passed? Yes

Complete the items listed below:

Roess

2 systems, 1 in attic and 1 in crawlspace, Check electrical connections at final.



Inspection Record Printed: 07/26/2023

Inspection Date: 08/19/2008 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: PLUMBING ROUGH-IN

Inspector: Mike Owen

Passed? Yes

Complete the items listed below:

Corn



Inspection Record Printed: 07/26/2023

Inspection Date: 08/19/2008 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: NOTE

Inspector: Mike Owen

Passed? No

Complete the items listed below:

No framing done is leveling and packing down and adding to level celing area up ok to insulate



Inspection Record Printed: 07/26/2023

Inspection Date: 08/28/2008 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: ELECTRICAL ROUGH-IN

Inspector: Mike Owen

Passed? Yes

Complete the items listed below:

Payne

1.Add receptacle aon wall beside plumbing chase.

2.Install smoke detectors.

***Check at insulation inspection

OK per keh 9/3/08



Inspection Record Printed: 07/26/2023

Inspection Date: 09/03/2008 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: INSULATION

Inspector: Ken Hyatt

Passed? Yes

Complete the items listed below:

Owner



Inspection Record Printed: 07/26/2023

Inspection Date: 10/15/2010 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: CHANGE OF CONTRACTOR

Inspector:

Passed? Yes

Complete the items listed below:

Change of electrical contractor placed in file.



Inspection Record Printed: 07/26/2023

Inspection Date: 11/08/2010 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: ELECTRICAL FINAL

Inspector: Wayne Cheek

Passed? Yes

Complete the items listed below:

RC

1. Need GFCI rec. at rear porch & label outside panel.



Inspection Record Printed: 07/26/2023

Inspection Date: 11/08/2010 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: PLUMBING FINAL

Inspector: Wayne Cheek

Passed? Yes

Complete the items listed below:

Corn



Inspection Record Printed: 07/26/2023

Inspection Date: 11/08/2010 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: MECHANICAL FINAL

Inspector: Wayne Cheek

Passed? Yes

Complete the items listed below:

Roess



Inspection Record Printed: 07/26/2023

Inspection Date: 11/12/2010 Permit Number: BRRA08-132

Address: 208 Hanty Branch Hill Road

Brevard, NC 28712

Applicant: Andrew Hamilton

Directions: 276S, Past Barclay, next L is Johnson, sharp L onto Johnson, immediately go R up Hanty

Branch Hill, dead end into house. 208 Hanty Branch Hill Road.

Inspection Type: BUILDING FINAL

Inspector: Wayne Cheek

Passed? Yes

Complete the items listed below:

Hamilton